Keep meters free of snow.

Snow and ice buildup on gas meters is a serious safety hazard. Make sure yours is clean.